
The side mullion is aligned with the adjacent wall
The mullion on the profile line is embedded in the wall instead of aligning with it
Core and Shell : Walls : Curtain Wall : CCP_Curtain Wall 2 (Stair Towers & Cut)


I try to align the profile to the wall and lock the constraint
Core and Shell : Walls : Basic Wall : CCP_METAL PANEL-01 - 12" : Reference


The curtainwall mullion snaps back into the adjacent wall instead of aligning with the edge
Core and Shell : Walls : Curtain Wall : CCP_Curtain Wall 2 (Stair Towers & Cut)